ACME COMPANY CONDO INSPECTION CHECKLIST TEMPLATE ACME



Millstone Avenue - Rutherford | Millstone Avenue,

WEDNESDAY 17TH SEPTEMBER 2025

SUMMARY

The regular maintenance inspection identified failed repairs by the previous owner. Furthermore, critical safety hazards were found with the breaker box in the laundry closet. The patio deck boards also show signs of severe rot and splintering.

A qualified contractor has been assigned to rectify all these deficiencies to protect the property's value and ensure the safety of the tenants.


Plumbing					
Q#	QUESTION	response			
1.	Are the pipe connections checked?	YES			
2.	Are leaks or potential leaks thoroughly examined?	YES			
3.	Is the condition of sinks, toilets, showers, and bathtubs assessed?	YES			
4	Were faulty repairs performed by previous owners identified?	NO			



17 Sep 25 12:11 PM

Electrical					
Q#	QUESTION	RESPONSE			
5.	Is faulty wiring inspected?	YES			
6.	Are loose outlets or light switches examined?	YES			
7.	Is any frayed or damaged wiring identified during the inspection?	YES			
8.	Is the condition of the breaker box good?	NO			

ACME COMPANY CONDO INSPECTION CHECKLIST TEMPLATE



17 Sep 25 12:16 PM

Stru	Structural					
Q#	QUESTION	response				
9.	Is the condition of door and window seals evaluated?	YES				
10.	Are signs of water damage looked for?	YES				
11.	Are signs of moisture or mold assessed?	NO				
12.	Are cracks in the ceiling or walls inspected?	YES				
13.	Is the condition of shared walls checked?	YES				

HVAC

Q# QUESTION RESPONSE

14. Is the HVAC system evaluated, and if it's in your unit, does the inspector provide an assessment of its condition?

YES

Miscellaneous

Q#	QUESTION	RESPONSE
15.	How is the deck/patio condition assessed?	NO

ACME COMPANY CONDO INSPECTION CHECKLIST TEMPLATE



17 Sep 25 12:22 PM

16.	If your unit has an attic, is it inspected, or if the common attic shares	YES
	a wall with your unit and is accessible to the inspector?	

17. Is the roof inspected, especially if you're on the top floor and it's YES accessible?

н						A 0	\circ		•
		NV.	NV/		-	Λ Ι -	\mathbf{n}		 \sim
	w	8 A 7	- N/A	NTS	\sim	$\mathbf{A} \mathbf{U}$		`	

Plumbing >> Plumbing	PRIORITY	Medium	
(AC10072) Were fau		20 Sep 25	
FINDINGS	'No'	ASSIGNEE	Jennifer Hunt

ACTION REQUIRED

Water staining below. Have a licensed plumber inspect and professionally repair the faulty drain pipe to prevent further water damage.

Electrical >> Electrical PRIORITY High

(AC10073) Is the condition of the breaker box good?

DUE DATE 18 Sep 25

ASSIGNEE Jennifer Hunt

FINDINGS 'No'

The breaker box in the laundry closet has a cracked circuit breaker switch. Replace the cracked circuit breaker switch to ensure the electrical panel is safe and compliant with code.

Structural >> Structural		PRIORITY	Low
(AC10074) Are signs of moisture or mold assessed?			23 Sep 25
FINDINGS	'No'	ASSIGNEE	Jennifer Hunt

ACTION REQUIRED

The basement utility closet shows visible signs of water staining and a musty odor. Identify and repair the source of the moisture leak (if any). Then, professionally remediate all affected materials to remove mold and mildew.

MILLSTONE AVENUE -**RUTHERFORD**

ACME COMPANY CONDO INSPECTION CHECKLIST TEMPLATE

17 SEP 25

Miscellaneous >> Miscellaneous

(AC10075) How is the deck/patio condition assessed?

PRIORITY DUE DATE ASSIGNEE

Medium 20 Sep 25 Jennifer Hunt

FINDINGS

'No'

The patio deck boards show evidence of severe splintering and rot near ACTION REQUIRED the foundation. Replace all rotted and splintered deck boards and apply a

protective sealant.

DECLARATION

Auditor (Jennifer Hunt) **AUDITOR'S LOCATION**